

試驗報告



報告編號：TS-24-00060

C-24-00397

頁數：1 OF 1

報告發行日期：113 年 01 月 17 日

工程委託供樣送會收試試驗備
 名稱：自測
 單位：光隆鋼鐵股份有限公司
 廠商：光隆鋼鐵股份有限公司/光隆摩擦焊股份有限公司
 稱：續接器
 人員：光隆鋼鐵股份有限公司/光隆摩擦焊股份有限公司-陳宜君(01051636)
 人員：NA
 日期：113 年 01 月 05 日 16 時 41 分
 日期：113 年 01 月 17 日 16 時 08 分
 方法：ASTM A1034/A1034M-10a
 註：1.以上資料(送驗人員、會驗人員、試驗方法、試驗數量、收件日期及試驗日期除外)及下述報告內容標示#處係由顧客提供
 2.除非另有說明，此報告結果僅適用於收取之試驗件
 未經本公司事先書面同意，此報告不可部分複製
 3.收件方式為實驗室收件；收件地點：同實驗室地址
 4.本實驗室為公共工程材料實驗室認證服務計畫認可實驗室

試驗結果：

一、續接器抗拉試驗：(0→拉斷)


試件編號	#符號	抗拉強度	斷裂位置
		N/mm ²	
D19-AU1	SD420W	655	斷鋼筋
D22-AU1	SD420W	667	斷鋼筋
D25-AU1	SD420W	638	斷鋼筋
D32-AU1	SD420W	652	斷鋼筋

註：1.樣品描述：已組裝續接器。

2.本實驗室執行試驗之地點同實驗室地址。

----- oOo -----

本報告若有提供規範值時，該規範值僅供參考，合格之判定以委託單位實際要求為準。



報告簽署人

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com.tw/TermsandConditions> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com.tw/TermsandConditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.